

Project Work Plan


Remove sediment and voluntary growth from inlets and outlets

Small trees and other undesirable woody growth can damage the structures or block the free flow of stormwater. Sediment buildup in the structures can also impair the flow of stormwater. **This project will be ongoing through 2015.**



Remove voluntary growth around ponds

Roots from invasive trees and brush can cause erosion issues along pond embankments. Undesirable woody growth can affect the aesthetics and the functionality of the ponds. **This project will be ongoing through 2015.**



Remove excess sediment from 2 ponds (dredging)

Sediment accumulation can affect proper functionality of the pond by reducing the capacity for which it was designed. **This project will be scheduled sometime in the future.**